



Installation Guidelines

Substation Style Current and Voltage Sensor



Insulation Class	Current Only P/N	Current & Voltage P/N
15kV	965x/Syz00	965x/Syz01
25kV	966x/Syz00	966x/Syz01
35kV	967x/Syz00	967x/Syz01
46kV	9680/Syz00	9680/Syz01

! DANGER

The sensor must be solidly grounded to earth before it is energized. Connection to the phase conductor will energize the sensor and will result in high voltage across the output unless grounded. Failure to ground before energizing can result in serious injury or death.

! DANGER

Sensor must be applied within its electrical and mechanical ratings. Application of sensor in excess of its ratings can result in immediate or delayed electrical or mechanical failure. Failure to apply the sensor within its ratings can result in serious injury or death, or in premature failure of the sensor.

! DANGER

Do not drop. While extremely durable, the sensor is cast from a material that can fracture if dropped onto a hard surface. Fractures can result in either catastrophic failure of the sensor upon energization resulting in serious injury or death, or in premature failure of the sensor.

! CAUTION

Sensor must remain in packaging during transportation to installation site. Transportation of the sensor without its protective packaging may result in chips, cracks, or fractures to the sensor body. Physical damage can result in premature failure of the sensor or reduced electrical ratings.

! CAUTION

Both the sensor cable connectors and the cable connector located on the sensor must remain dry and protected from inclement weather. The connectors are weatherproof once joined, but may allow moisture in the cable when the male or female connectors are left exposed to the elements. Moisture in the cable will result in inaccurate measurement readings.

! WARNING

DO NOT HIPOT. HIPOT (high potential) testing will thermally damage the resistor assemblies in the sensor causing permanent damage. HIPOT testing voids the sensor's warranty. If a HIPOT test is necessary, contact Lindsey for alternate product intended for HIPOT.

Specifications:

ELECTRICAL RATINGS				
Catalog Number Sequence	965x/Syz0...	966x/Syz0...	967x/Syz0...	9680/Syz0...
Insulation Class	15kV	25kV	35kV	46kV
Impulse (BIL)	110kV	150kV	200kV	250kV
Leakage Distance	15.0 in.	19.3 in.	28.1 in.	39.0 in.
Dry Arc Distance	8.3 in.	10.6 in.	15.0 in.	17.1 in.
Overall Height	14.1 in.	16.2 in.	20.6 in.	22.5 in.
Withstand* (60Hz, 1 min.)	34kV	40kV	50kV	65kV
Corona (extinction)	11kV	19kV	26kV	33kV

*Current only sensors

MECHANICAL RATINGS				
Insulation Class	15kV	25kV	35kV	46kV
Cantilever Strength	2,800 lbs.	2,800 lbs.	2,800 lbs.	2,800 lbs.
Weight	37 lbs.	45 lbs.	59 lbs.	52 lbs.
Shipping Weight	40 lbs.	48 lbs.	62 lbs.	61 lbs.

Characteristics:

The Lindsey Tube-Top Style Current and Voltage Monitoring Insulator (CVMI) is designed to be installed on a de-energized line. The conductor passes through the central tube produces current sensing. Clamping of the conductor to the central tube connects to the voltage sensing circuit. No clamping is required for current only sensors. The CVMI can be installed in either a horizontal or vertical line post configuration, depending on the accessory hardware used. Following the instructions below will insure a safe and simple installation.

Installation:

1. Using the sensor catalog number, use the Specifications tables to ensure the sensor is being applied in accordance with its ratings.
2. Pre-assemble the hardware accessories to the insulator. This may include the bottom-mounting stud and/or the horizontal mounting base. See Table 1. The actual hardware will depend on the specific installation.
3. If the CVMI is replacing an existing insulator, raise the conductor away from the insulator using approved utility practices and remove the existing insulator.
4. Mount the Lindsey CVMI with H1 identification labeled on the sensor body (opposite side of connector) closest to the supply or the substation direction.
5. Connect the base of the CVMI to ground.
6. Plug the signal cable from the base of the pole into the connector at the base of the insulator.
7. Pass the bare conductor through the stainless steel tube in the head of the CVMI.
8. If the stainless steel tube of the CVMI is equipped with an optional "U"-bolt clamp, install and tighten the clamp. All normal procedures to minimize contact resistance, such as brushing the conductor and applying anti-corrosion grease, should be used.

Table 1: Accessories for Tube-Top Style Sensor

PART #	DESCRIPTION
2004	Horizontal mounting base
R-13109SS	Stainless steel U-bolt clamp for use with voltage sensing tube top CVMI
2040	3/4" x 2 3/16" mounting stud for metal cross-arms
2041	3/4" x 7" mounting stud for wood cross-arms

NOTE: If the CVMI is a voltage sensing unit the clamp (P/N R-13109SS) must be used to obtain proper sensing.